| | Property is: Single Fam | nily X D | uplex | Other | |
|--------------|--------------------------------------|-----------------------|----------|--|----------------------------------|
| Date: | 8/26/2010 | , 5 | аріол | | |
| | - | — ealth and safety | issues | The City of Milwaukee, the Redevelopment Auth | ority, and their representatives |
| ake no respo | onsibility for problems discovered a | after the inspect | ion date | e, or for omissions through error or oversight. The eral Block Grant or HOME programs. | - |
| Exterior (| Condition Report | | | | |
| _ocation | Required Work | | | Note/Comments | Cost |
| Site | Landscaping | n/a Ye | es X | Self Help Tree Removal | \$ 500 |
| | Steps/Handrails | n/a X Ye | es | | \$ |
| | Service walks | n/a X Ye | es 🗌 | | \$ |
| | Fencing | n/a X Ye | es 🗌 | | \$ |
| | Parking | n/a X Ye | es 🗌 | | \$ |
| | Retaining walls | n/a X Ye | es 🗌 | | \$ |
| | Other | n/a X Ye | es 🗌 | | \$ |
| | Other | n/a X Ye | es 🗌 | | \$ |
| Garage | Singles: repair | n/a X Ye | es 🗍 | | \$ |
| N/A | | | | | |
| N/A | Shingles: Roof over existing | | es | | \$ |
| | Shingles:Tear off & re-roof | n/a X Ye | | | \$ |
| | Gutters/downspouts | n/a X Ye | es 🔝 | | \$ |
| | Flashing | n/a X Ye | es | | \$ |
| | Eaves | n/a X Ye | es | | \$ |
| | Siding | n/a X Ye | es 🗌 | | \$ |
| | Doors | n/a X Ye | es 🗌 | | \$ |
| | Windows | n/a X Ye | es 🗌 | | \$ |
| | Slab | n/a X Ye | es 🗌 | | \$ |
| | Paint | n/a X Ye | es 🗌 | | \$ |
| | Electrical | n/a X Ye | es 🔲 | | \$ |
| | Other | n/a Ye | es 🗌 | | \$ |
| Porches | Roof | n/a 🗶 Ye | es 🗌 | | \$ |
| | Deck-upper | n/a X Ye | es 🗍 | | \$ |
| | Decklower | n/a X Ye | | | \$ |
| | Steps/handrails | n/a X Ye | | | \$ |
| | Ceiling | n/a X Ye | | | \$ |
| | Guardrails | | es 🗍 | | \$ |
| | Structural | n/a X Ye | | | \$ |
| | Paint | n/a X Ye | | | \$ |

n/a Yes

Other

\$

House

| Chimney | n/a X Yes | \$ |
|------------------------------|--------------------------|----------------|
| Shingles: repair | n/a X Yes | \$ |
| Shingles: Roof over existing | n/a X Yes | \$ |
| Shingles:Tear off & re-roof | n/a X Yes | \$ |
| Gutters/downspouts | n/a Yes X Repairs | \$ 400.00 |
| Flashing | n/a X Yes | \$ |
| Eaves | n/a X Yes | \$ |
| Siding | n/a Yes X Replace | \$ 3,000.00 |
| Storm Doors | n/a Yes X 2 Doors | \$ 400.00 |
| Prime ("main") Doors | n/a X Yes | \$ |
| Storm Windows | n/a X Yes | \$ |
| Prime ("main") Windows | n/a Yes X 3 Main Windows | \$ 1,200.00 |
| Paint | n/a Yes X Eaves & Trim | \$ 700.00 |
| Foundation | n/a X Yes | \$ |
| Electrical | n/a X Yes | \$ |
| Other | n/a Yes | \$ |
| Other | n/a Yes | \$ |
| Other | n/a Yes | \$ |
| Other | n/a Yes | \$ |

Exterior: Estimated Cost:* \$
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

6,200.00

| Interior Co | ondition Report | | | | | |
|-----------------------|--|--------|------|-----|----------------------------|----------------|
| | Unit: Entire unit (single family) Upper unit of duplex | X | | | Lower unit of duplex Other | |
| Mechanical Heating | Required Work | | | | _ | |
| | Repair/replace boiler | n/a > | (Ye | s | | \$ |
| | Repair radiation | n/a | Υe | s | | \$ |
| | Repair/replace furnace | n/a | Ye | s X | Replace Complete System | \$ 6,000.00 |
| | Repair ductwork | n/a | Υe | s X | | \$ |
| | Replace thermostat | n/a | Υe | s X | | \$ |
| | Repair/replace grilles | n/a 🕽 | (Ye | s 🗌 | | \$ |
| Electrical | Tune boiler/furn. insp ht exchange | €n/a > | ⟨ Y∈ | s | | \$ |
| Liectrical | Repair/replace receptacles | n/a | Υe | s | | \$ |
| | Repair/replace switches | n/a > | Υe | s | | \$ |
| | Repair/replace fixtures | n/a > | (Ye | s | | \$ |
| | Install outlets and circuits | n/a > | (Ye | s | | \$ |
| | Install outlets and circuits | n/a > | Υe | s | | \$ |
| | Install outlets and circuits | n/a 🕽 | Υe | s | | \$ |
| | Install outlets and circuits | n/a 🕽 | Υe | s | | \$ |
| | Upgrade service | n/a 🕽 | Υe | s | | \$ |
| | Other | n/a | Υe | s | | \$ |
| | Other | n/a | Υe | s | | \$ |
| Plumbing | Repair/replace kitchen sink | n/a | Ye | s X | | \$ |
| | Repair/replace kitchen sink fauce | ın/a | Υe | s X | | \$ |
| | Repair/replace tub | n/a | Ye | s X | | \$ |
| | Repair/replace tub faucet | n/a | Υe | s X | | \$ |
| | Repair/replace toilet | n/a | Ye | s X | | \$ |
| | Repair/replace lavatory | n/a | Ye | s X | | \$ |
| | Repair/replace lavatory faucet | n/a | Ye | s X | | \$ |
| | Repair/replace wash tub | n/a | Ye | s X | | \$ |
| | Repair/replace wash tub faucet | n/a | Υe | sχ | | \$ |
| | Unclog piping: | n/a 🕽 | ζ Ye | s | | \$ |
| | Repair drain/waste/vent piping | n/a | Ye | sχ | | \$ 600.00 |
| | Repair water piping | n/a | Υe | sχ | | \$ 900.00 |
| | Repair/replace water heater | n/a | Υe | sχ | Replace | \$ 800.00 |
| | Other | n/a | Υe | sχ | Complete Kitchen | \$ 1,000.00 |

n/a Yes X Complete Bath

Other

\$

800.00

| Windows | | | | | |
|--------------|-----------------------------------|-----------------|------------------------------------|--------------|-----------|
| | Replace broken glass | n/a Yes X | 8 Windows | \$ | 400.00 |
| | Repair or replace sash | n/a X Yes |] | \$ | |
| Doors | Repair or replace doors | n/a χ Yes |] | \$ | |
| | Repair or repl. locks/latches | n/a X Yes | Self Help | \$ | |
| Walls/Ceilin | gs Repair or repl. @ defective | n/a Yes X | Repairs | \$ | 500.00 |
| | repair or repr. & derective | 11/4 [] 163 [X | Repairs | Ψ | 300.00 |
| Paint | Repair or repl. @ defective | n/a Yes χ | Complete Unit | \$ | 1,000.00 |
| Fire Safety | | | | | |
| • | Install smoke alarm:bsmt. | n/a X Yes | Self Help | \$ | |
| | Install smoke alarm: 1st flr. | n/a X Yes | Self Help | \$ | |
| | Install smoke alarm: 2nd flr. | n/a X Yes | Self Help | \$ | |
| Handrails | Repair/replace defective | n/a Yes X | Self Help | \$ | 75.00 |
| Stairs | Repair defective | n/a X Yes | 1 | \$ | |
| Floors | | | | • | 0.500.00 |
| Other | Repair defective | n/a Yes X | Complete Unit | \$ | 2,500.00 |
| | - | n/a Yes |] | \$ | |
| | | n/a Yes |] | \$ | |
| | | n/a Yes |] | \$ | |
| | | n/a Yes |] | \$ | |
| | | | Interior: Estimated Cost: | \$ | 14,575.00 |
| | | | Total Exterior and Interior Cost:* | \$ | 20,775.00 |
| | | | Total Exterior and interior Goots | _ | |

Prepared by: S. Denny / Inspected by: Paul Geboy Date: 8/27/10

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway. If you will be occupying the home, you can get free lead-safe training from the Health Department! Call 286-5119 to schedule on-site training.

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.